

Documentation

We may require documentation including but not limited to the following:

(a) detail of the specifications of the product being removed from the tank creating the roof out of float condition and the specifications of the product intended to refill the tank to assure air emission compliance before allowing the tank roof landing event (i.e., Certificate(s) of Analysis); and/or

(b) detail sufficient to demonstrate that a roof landing will not last longer than seventy-two (72) hours. During the seventy-two (72) hour period, The Customer must either refloat the roof with a different quality Product than was originally present in the tank or strip and control the tank as per TCEQ guidelines.

(c) When refilling the tank, the Product amount reintroduced must be of the amount to make the roof buoyant. Tank refill rates will be tank specific and will be dependent upon the time of year when refill occurs. The refill rate is only applicable during the time when the roof is out of float.